



FTT 3 Metre Cube Spare Parts List

<i>Part Number</i>	<i>Part type</i>	<i>Part Name</i>	<i>Unit Price</i>	<i>Notes</i>	<i>Instrument</i>
3157	Detector	Photo detector	POA	Includes resistor and potentiometer network only. Order 5080 for complete assembly	3 m Cube
5080	Detector	Complete photocell assembly	POA	Includes photo detector (3157) built into housing	3 m Cube
3137	Fuel Tray	Fuel Tray	POA		3 m Cube
4403	Lamp	Light source assembly	POA	Dedo Lamp	3 m Cube
4503	Lamp	M28 equivalent bulb	POA		3 m Cube
3999	Manual	User's guide for 3 metre cube	POA		3 m Cube
3153	Optical filter	Filter 0.3 ND	POA	No calibration certificate	3 m Cube
3154	Optical filter	Filter 0.6 ND	POA	No calibration certificate	3 m Cube
5079	PSU	12 volt stabilised power supply assembly	POA	Power supply in case	3 m Cube
3143	Stand	Stand adaptor and bolt	POA	For attaching photo detector assembly (5080) to stand (4522)	3 m Cube
3156	Stand	Lamp adaptor and peg	POA	For attaching light source assembly (4403) to stand (4522)	3 m Cube
4522	Stand	Stand for detector or lamp assembly	POA	Does not include mounting parts	3 m Cube